

Phoenix Goodyear Airport

Airport Surface Map Field Elevation: 968 ft MSL Location 33° 25.3' N 112° 22.5' W

TN MN Displaced Threshold: Rwy 21 - 6400 ff. available Parked Aircraft FAA Tower and Beacon Beacon

Pattern Altitude
ATIS
Tower
Ground Control
Unicom
FSS: Prescott
Luke Radar

Frequencies subject to change, not for navigational use.

revised 09/01

Phoenix Goodyear Airport

Hours of Operation 6:00 am to 9:00 pm Local

Goodyear Airport Operations (623) 932-4550
Airport FAX (623	932-2716
Sky Harbor Communications Emergency Line (602	273-3311

Services Available

Chevron Fuel	Computerized Weather
100LL	PILOTbrief VECTOR
ૐ Jet A	Flight Planning Room
Aux power Unit	Conference Room

Local Car Rental and Hotels (Area Code: 623)

Avis	(623) 536-3271	Hampton Inn	(623) 536-1313
Enterprise	(623) 932-2501	Holiday Inn Express	(623) 535-1313
Hertz	(623) 872-1368	Wigwam Resort	(623) 935-3811

Recommended Noise Abatement Procedures

- Remain above pattern altitude until necessary to descend lower for landing
- Avoid long, low, power-on approaches
- * Remain at or above indicated glide slope on final approach
- Avoid noise sensitive areas west and northeast
- Runway 21 designated calm wind runway
- Climb initially at aircraft's best angle of climb (Vx) until reaching 2000 feet MSL, consistent with safety, then reduce to cruise climb setting
- No downward departures
- Upon departing Runway 03 make immediate right turn or 45 degree left turn before crossing Litchfield Road
- Cross I-10 at or above 2000 feet MSL

NOTE: The above procedures are recommended for departures at Phoenix Goodyear Airport.

They are not intended to abrogate safe aircraft operations.